


MESTRA[®]
CALENTADOR DE CERA
WAW HEATER
CHAUFFE-CIRE
R-080070



MESTRA®
CALENTADOR DE CERA
WAX HEATER
CHAUFFE-CIRE
R-080070 / R-080070B

Nº	Ref.	DESCRIPCIÓN	DESCRIPTION
1	080070-01	Carcasa calentador	Heater Housing
2	080070-02	Tornillo tapa	Cover screw
3	080070-03	Tornillo cuba	Container screw
4	080070-04	Cuba	Container
5	080070-05	Junta silicona	Silicone gasket
6	080070-06	Resistencia 230V	Resistor 230V
	080070-07	Resistencia 115V	Resistor 115V
7	080070-10	Cable 230V	Cable 230V
	080070-10B	Cable 115V	Cable 115V
8	050364-04	Patas de goma	Rubber legs
9	080070-22	Contactador	Contactador
10	080070-23	Tornillo contactor	Contactador screw
11	080070-26	Tapa de la carcasa	Housing cover
12	080070-12	Pasa cables	Cable bushing
13	080070-13	Tornillo	Screw
14	050310-14	Tuerca	Nut
16	080070-16	Tapa lateral izquierda	Left lateral cover
17	080070-20	Tapa lateral derecha	Rigth lateral cover
18	080010-20	Interruptor	Switch
19	080070-19	Tornillo de masa	Ground screw